


★ One Tool (Hex Wrench) 

STEPS


(1) Hardware



(2) Printed Graphic Fabric Banner



(3) LED Ladder Light & Switching Power Supply




(4) Hex Wrench, Screw A & Hook.




STEP 01

Connect to make long poles according to labelings.




STEP 02

Connect long poles with corner poles according to labelings.




STEPS

Connect long poles with corner poles according to labelings.




STEP 03

Interconnect corner poles to make column frame according to labelings.



STEP 04



Connect short poles around column frame.



STEPS



STEP 05

Hang LED ladder light into poles' holes.



STEP 06

Connect switching power supply with wires.



STEP 07

Wrap column frame with fabric banner & zip up at corner.

